



Ignition Switch Malfunction Causes Multiple Symptoms

Product: Groundsmaster® 360

April 27, 2012

(Revised- new part number)

Affected Units:

Models:

Serial Numbers:

| | |
|-------|---------------------|
| 30534 | 311000101-312000127 |
| 30535 | 311000101-312000110 |
| 30536 | 311000101-312000110 |
| 30537 | 311000101-312000140 |
| 30538 | 311000101-312000406 |
| 30539 | 311000101-312000155 |
| 30540 | 311000101-312000112 |
| 30541 | 311000101-312000401 |
| 30542 | 311000101-312000122 |
| 31222 | 312000101-312000108 |
| 31223 | 312000101-312000110 |


Situation:

Several electrical issues have been found to be caused by malfunction of factory-installed Ignition Switch ASM, including:

- Constant or intermittent failure of factory-installed Ignition Switch ASM
- Unintentional engagement of the engine starter or starter overheat/failure while key switch is in the Run position
- Intermittent flickering of glow plug and/or diagnostic lights
- Failure of Stop Solenoid
- Damage/overheating of Wire Harness

Corrective Action:

If any of the above referenced conditions are experienced, the factory-installed Ignition Switch Assembly must be replaced with updated Ignition Switch ASM (121-5357) to correct the issue.



Please contact your local Toro Commercial Products Distributor to obtain Ignition Switch (121-5357) and to learn more about this issue and its resolution. Reference Toro Commercial Product Service Bulletin Rotaries #16-19 when making your inquiry.