



**Customer Service Bulletin
Commercial Business Group**

GREENSMASTER[®] 3200 and 3200-D

<u>Model/Serial Range:</u>	<u>Model Number:</u>	<u>Serial Numbers:</u>
	04380	70101-70184
	04381	70197-70601

Subject: Reel supply hose failure inspection and rework.

The supply hose used in the reel circuit in some of the units listed above may develop a leak due to a problem in the rubber curing process of the inner liner by the hose manufacturer. Affected hoses have date code 1Q97 stamped on the lay line of the Hydraulic Hose 94-1332. Contact your local TORO distributor to arrange for an inspection of your unit and replacement of any affected hoses.