



Customer Service Bulletin Commercial Business Group

Reelmaster® 3100-D Product

<u>Model/Serial Range:</u>	<u>Model Number:</u>	<u>Serial Numbers:</u>
	03200	90101-90342
	03201	90101-90951

Subject: Slope Angle Indicator (100-4917) - Rework

Toro has received reports from the field of a few Reelmaster 3100-D side hill tipovers. No injuries have been reported. Investigation by Toro personnel into these circumstances indicated that in all cases the Reelmaster 3100-D was being used beyond its intended application and the operator had failed to comply with Toro's clearly stated side hill maximum angle of 25 degrees.

All Reelmaster 3100-D products listed above will be reworked by having a Slope Angle Indicator installed on the Steering Tube to increase the Operator's awareness of the terrain. See sample of Slope Indicator below. Additionally, customers will receive information from Distributor Sales Personnel regarding appropriate safety precautions and operating procedures.

For additional information please contact your local Toro Distributor.

