



Customer Service Bulletin Commercial Business Group

Groundsmaster® 300 Series

<u>Model/Serial Range:</u>	<u>Model Number:</u>	<u>Serial Numbers:</u>
	30741	00000-60161
	30789	00000-60237
	30788	00000-60443
	30795	00000-60268
	30739	00000-60120
	30780/30787/30782	00000-99999
	30774/30773/30781	00000-00000

Subject: Availability of repair parts to correct PTO Support Plate frame damage

A cracked PTO Support Plate is caused by repeated impacts against solid objects, such as tree roots or substantial loose debris. This damage can usually be repaired by welding the visible cracks. If the shaft support area is broken out, replacement parts are available to repair and reinforce the affected frame area.

One Pivot Hub 21-1210 and one Stiffener Plate 94-6870 are required to perform the repair shown below.

