



Customer Service Bulletin Commercial Business Group

Workman[®] 3000/4000 Vehicles

Date: August 17, 2005

<u>Model/Serial Range:</u>	<u>Model Number:</u>	<u>Serial Numbers:</u>
	07360	250000101 - 250000226
	07361	250000101 - 250000636
	7361TC	250000101 - 250000135
	07362	250000101 - 250000299
	362TC	250000101 - 250000297
	07363	250000101 - 250000295
	07364	250000101 - 250000191
	07364TC	250000101 - 250000185
	07365	250000101 - 250000200

Subject: Possible missing weld at floor plate below clutch pedal.

The floor plate may be missing a weld just forward of the stationary anchor point for the clutch cable. If this weld is missing, the clutch engage forces may eventually deform the floor plate upwards and change the operation of the clutch.

Inspect the unit for the condition pictured below or a missing weld in the area identified. If the area is deformed or the weld is missing, contact your local Toro Commercial Products Distributor to arrange for repair.

