



Potential PTO Hose Damage

Product: Groundsmaster® 4000

May 18, 2012

Affected Units:

Models:

Serial Numbers:

GM 4000

30412

290000200-290009999

30446

310000001-311009999

30448


310000001-311009999


Situation:

Wing deck PTO hoses may rub on wing deck mount.

Instructions:

Inspect PTO hoses for signs of rubbing on the deck mount casting, and install Hose Guides (120-0480-03 RH and 120-0481-03 LH) to isolate the hoses from the wing deck casting.





If you experience any problems in installing hose guides please contact your local Toro distributor.