



## The Rear Left Fender Melts

**Product: HD Series Workman®**

**April 4, 2014**

**Affected Units:**

**Models:**

**Serial Numbers:**

07383	313000101-314009999
07384(TC)	313000101-314009999
07385(TC)	313000101-314009999
07386(TC)	313000101-314009999
07387(TC)	313000101-314009999

**Situation:**

In stationary use applications, heat emitted from the engine exhaust can cause heat distortion damage to the rear left fender of the Workman vehicle.

**Instructions:**

A Tailpipe Extension Kit (127-7397) has been developed to address this issue. Use of this kit is recommended anytime the 200 Gallon Sprayer, Topdresser and Hand Throttle accessories are installed to ensure fender damage does not occur in situations where the engine is running and the vehicle remains still or driven very slowly.

Please contact your local Toro Commercial Products Distributor for more information on this kit and its installation. Please reference Commercial Service Bulletin Vehicles 05-13 when making your inquiry.