Customer Service Bulletin
Commercial Business Group

Workman® Sprayer Sonic Boom

Model/Serial Range:	Model Number:	Serial Numbers:
	41036	not applicable

Subject: **Change to Sonic Boom Wire Harness.**

The colors of the Power Assembly leads changed during the 1993 model year. Originally, the power wire assembly used a Black wire and a White wire. The wires were routed as follows:

Black Wire: To the Power Source
White Wire: To Ground

The power wire assembly currently uses a Red wire and a Black wire. The NEW wires are routed as follows:

Red Wire: To the Power Source
Black Wire: To Ground

All current manuals for the 1993 model year are correct in showing the new Red/Black power wire assembly. The power wires regardless of the color of the harness are tagged with an "+" or "-" to ensure proper installation. See illustration below.



Ref: 17-03 Copyright©, 1995. The Toro Company