



Customer Service Bulletin Commercial Business Group

Groundsmaster® 7200 Series

Date: March 5, 2007

<u>Model/Serial Range:</u>	<u>Model Number:</u>	<u>Serial Numbers:</u>
Road Light Kit	30374	260000101-270000279

Subject: 10 Amp Road Light Kit Fuse Failures.

Early versions of Groundsmaster 7200/7210's with a Road Light Kit (30374) installed were equipped with a 10 amp fuse to protect the Light circuit.

Power demands of the Road Light kit were re-evaluated, and it has been determined that the correct fuse size should be increased to 15 amp rating (vs. original 10 amp).

If the 10 Amp Road Light Fuse fails, it should be replaced with a 15 amp rated ATC blade style fuse. Obtain replacement fuses locally (if required).