



# Traction Hose Contacts Steering Fork

**Product:** Sand Pro 3040/5040®

**October 21, 2015**

**Affected Units:**

**Models:**

**Serial Numbers:**

**Sand Pro 5040**

08705

312000101-315000381

**Sand Pro 3040**

08703

312000101-315000339

**Situation:**

The front wheel motor traction hoses may contact the back of the steering fork during turns causing damage to the hose.

**Instructions:**

If the front wheel motor hose (119-6742 HYD HOSE ASM or 119-6747 HYD HOSE ASM) is damaged by the steering fork, repair the hose and install the updated Hose Guide to prevent any future contact between the fork and the traction hoses.

Replace the Hose Guide (green) with an updated Hose Guide (130-7873)(yellow). The updated Hose Guide will position so they will no longer contact the rear corner of the steering fork during turns.

