



HoverPro Machines

Model No. 02602—Serial No. 315000001 and Up

Model No. 02604—Serial No. 315000001 and Up

Model No. 02606—Serial No. 315000001 and Up

Model No. 02610—Serial No. 315000001 and Up

Model No. 02611—Serial No. 315000001 and Up

Model No. 02612—Serial No. 315000001 and Up

Model No. 02615—Serial No. 315000001 and Up

Setup Instructions

Refer to the following chart for high idle specifications for your machine:

Model	Description	High Idle Specification
02602	HoverPro 450	3400 +0 / -100
02604	HoverPro 500	3100 +0 / -100
02606	HoverPro 550	3100 +0 / -100
02610	HoverPro 450	3700 +0 / -100
02611	HoverPro 550	3700 +0 / -100
02612	HoverPro 450	3100 +0 / -100
02615	HoverPro 400	5000 +0 / -100

