



HoverPro® 400, 450, and 550 Machines

Model No. 02610—Serial No. 410200000 and Up

Model No. 02611—Serial No. 408000000 and Up

Model No. 02615—Serial No. 408000000 and Up

Model No. 02616—Serial No. 400000000 and Up

Model No. 02617—Serial No. 400000000 and Up

Setup Instructions

Refer to the following chart for high idle specifications for your machine:

Model	Description	High Idle Specification
02610	HoverPro 450	3700 +0 / -100
02611	HoverPro 550	3700 +0 / -100
02615	HoverPro 400	5000 +0 / -100
02616	HoverPro 450	3100 +0 / -100
02617	HoverPro 550	3100 +0 / -100

