



## Customer Service Bulletin Commercial Business Group

---

### GREENSMASTER® 3200

<b><u>Model/Serial Range:</u></b>	<b><u>Model Number:</u></b>	<b><u>Serial Numbers:</u></b>
	04380	50001 - 70184

**Subject: Fuel Pump replacement program.**

The original Fuel Pump may not deliver enough fuel in heavy load or high ambient temperature conditions. In these situations you may experience low power or symptoms of fuel starvation. To correct this issue the original Fuel Pump on your unit should be replaced with Fuel Pump (825232). Contact your local Toro Distributor to arrange for a no charge conversion to this Fuel Pump.

Note: At the next recommended Fuel Filter replacement interval after this conversion, we suggest you use Fuel Filter (95-2926). Converting to this filter is not mandatory and in no way affects your warranty coverage, however the filter does provide superior filtration for long term protection for your investment. Units produced after the serial range listed above include the pump and filter improvements.