



Customer Service Bulletin Commercial Business Group

Greensmaster® 3200/3200-D

<u>Model/Serial Range:</u>	<u>Model Number:</u>	<u>Serial Numbers:</u>
	04380	50001-70184
	04381	50001-70743

Subject: Increasing floatation or travel of the cutting unit suspension.

If your greens have an unusually abrupt rise or step, the cutting unit suspension may reach its full vertical travel limit. In such conditions the cutting units may not completely follow the contour of the ground and result in uneven or uncut grass.

To accommodate cutting environments that have an abrupt rise or step, we now offer Suspension Update Kit (98-4611). This kit increases vertical travel of the suspension, which significantly improves the ability of the cutting units to follow ground contours.

Suspension Update Kit (98-4611) is available through your local Toro distributor.