



Customer Service Bulletin Commercial Business Group

Greensmaster® 3200/3200-D

<u>Model/Serial Range:</u>	<u>Model Number:</u>	<u>Serial Numbers:</u>
	04380	50001-70184
	04381	50001-70743

Subject: Center Cutting Unit Frame Interference.

Contact may occur between the center cutting unit carrier frame and the brake linkage, due to the limited available clearance. If the contact is significant, it may cause quality of cut concerns. Typically this is only an issue when a Groomer is installed.

If you notice significant contact as described above and it results in a quality of cut issue, an Adjustable Carrier Frame (98-4626) is now available to correct the condition. The adjustable frame allows the frame position to be altered so that the interference can be eliminated. Contact your local Toro distributor for additional details.