



Customer Service Bulletin Commercial Business Group

Reelmaster® 3100-D

<u>Model/Serial Range:</u>	<u>Model Numbers:</u>	<u>Serial Numbers:</u>
	03200	90000-200009999
	03201	90000-200009999

SUBJECT: Change to column bearing remedies steering wheel wobbling.

SITUATION: On earlier production Steering Control Assemblies a bushing was used to support the steering wheel. Forces applied while using the steering wheel for support climbing onto or off unit will wear this bushing, allowing the steering wheel to wobble / vacillate. Limiting use of the steering wheel as a handle will increase component life.

CORRECTION: Steering columns in current production use a bearing that provides improved support for the steering wheel. The bearing is not serviced separately. Column ASM (104-0475) should be used to service the Steering Control Assembly. Complete replacement of the Steering Control Assembly is not necessary. Orders for the original Column ASM parts will be cross-referenced to the current Column ASM (104-0475).

PARTS: Column ASM (104-0475) is currently available through your distributor.