

LED Light Kit TimeCutter[®] Max or TITAN[®] Riding Mower Model No. 147-8757

Installation Instructions

Installation

Loose Parts

Use the chart below to verify that all parts have been shipped.

Description	Qty.	Use
No parts required	-	Prepare the machine.
Light bracket	1	
Hex-washer-head thread forming screw (5/16 x 3/4 inch)	2	
LED light	1	Install the LED Light Kit.
Hex-washer-head screw	2	
Wire harness	1	
Cable tie	1	

Preparing the Machine

Gas Models Only

- 1. Park the machine on a level surface.
- 2. Disengage the blade-control switch.
- 3. Move the motion-control levers outward to the PARK position.
- 4. If equipped, engage the parking brake.
- 5. Shut off the machine and remove the key.
- 6. Wait for all moving parts to stop.
- 7. Allow machine components to cool.

Electric Models Only


- 1. Park the machine on a level surface.
- 2. Disengage the blade-control switch.
- 3. Move the motion-control levers outward to the NEUTRAL position.
- 4. Engage the parking brake.
- 5. Shut off the machine and remove the key.
- 6. Wait for all moving parts to stop.
- 7. Allow machine components to cool.
- 8. Remove the battery packs from the machine.




Installing the LED Light Kit

Note: For installation assistance, contact an Authorized Service Dealer.


1. Install the light bracket onto the front of the machine using the 2 hex-washer-head thread forming screws (5/16 x 3/4 inch).




2. Install the light to the light bracket using the 2 hex-washer-head screws.



3. Connect the wire harness to the back of the lights and secure the harness to the front frame rail using the harness clip.



- 1. Harness clip
- 4. Route the wire harness along the right frame rail, while securing the harness clips to the rail.



- 5. Cut the cable tie securing the auxiliary connector off the main harness and remove the auxiliary end plug.
- 6. Connect the light harness to the auxiliary connector.
- 7. Secure the kit wire harness to the machine wire harness using the cable tie.
- 8. Electric machines only: install the batteries.