



Customer Service Bulletin

Commercial Business Group

Groundsmaster[®] 325-D

<u>Model/Serial Range:</u>	<u>Model Number:</u>	<u>Serial Numbers:</u>
	30795	90101-90267
	30741	90101-90169

◆ Exempt units listed on the bottom of this Bulletin

Subject: 4WD-Rear Axle Wheel Rework.

The 4WD-Rear Axle Wheels were manufactured with a thin center section material. When mounted to the Rear Axle the Wheel lug nuts may seat against the Rear Axle Hub instead of the machined 60-degree cone of the center section. Although the wheel lug nuts are tight the wheel is loose. Continued operation of machine may cause eventual elongating of the Wheel mounting holes.

All affected units should have the Rear Axle Wheels replaced. Please contact your local Toro Distributor for further details.

The following units have already been corrected.

Model 30795

90188 - 90210, 90214 and 90216 - 90220

Model 30741

90101, 90126 - 90133, 90135 - 90144, 90147 - 90150, 90155, 90156, 90158, 90159 and 90162 - 90169