



Customer Service Bulletin Commercial Business Group

Groundsmaster[®] 580-D

Date: July 9, 2002

<u>Model/Serial Range:</u>	<u>Model Number:</u>	<u>Serial Numbers:</u>
	30580	00101 - 79999
	30581	80101 - 210099999

Subject: **Replacement Deck Spindle Assembly (69-8400).**

Situation: Rebuilding Spindle Assemblies is time consuming and can be unreliable if not performed properly.

Correction: A Spindle Assembly (69-8400) is now available to simplify installation and minimize machine “down time”. Using this Spindle Assembly to repair spindles, versus overhauling, reduces labor and ensures that the customer receives the additional benefit of new part.