



## **Multi Pro<sup>®</sup>, Maxi Pro<sup>®</sup>, and Workman<sup>®</sup> Sprayers**

<b>Model/Serial Range:</b>	<b><u>Model Number:</u></b>	<b><u>Serial Number:</u></b>
	3157 Series 5210 (MP 44)	00000-99999
	3157 Series 5211 (MP 44)	00000-99999
	3234 Series 5217 (MP 435)	00000-99999
	3235 Series 5215 (MP 418)	00000-99999
	3235 Series 5218 (MP 418)	00000-99999
	3257 Series 5222 (MP 440)	00000-99999
	3258 Series 5223 (MP 418)	00000-99999
	41502, 41514, 41101, 41105	00000-99999
	07200 and 07202	00000-99999
	07205 and 07206	00000-99999
	07210, 07215, and 07216	00000-99999

**Subject: Supplier has discontinued Sonic Boom Model 41036 and replacement parts.**

Our original supplier no longer offers Sonic Boom Model 41036 and will no longer provide replacement components to us. At the time of this printing, repair of the Sonar Control Head (42812) is currently offered by the supplier, however repairs are expensive and the time frame has been known to be lengthy (4-months). Also, Sonar Head (42803) is no longer available or repairable.

Although the original Sonic Boom replacement components may no longer exist, the current Toro manufactured and supported system is immediately available for installation. Should you experience a non-repairable type failure, this system is available as Sonic Boom Replacement Kit (95-9121).

Note: Some accessories may require relocation to accommodate this kit.

**Special Program Offering:**

To offset much of the cost of this conversion, Toro is offering a special program. A special "core" credit is currently offered through your local Toro distributor to counter some of the expense of this conversion. Credit is issued upon receipt of your original system (Sonar Control Head and both Sonar Heads) to your local Toro distributor. Contact your local Toro distributor for full program details.