



## Customer Service Bulletin Commercial Business Group

---

### Multi Pro<sup>®</sup> Spray Booms

Date: March 9, 2007



<u>Model Names:</u>	<u>Model Numbers:</u>	<u>Serial Numbers:</u>
Multi Pro	41xxx (ALL)	250009999 and Prior
Multi Pro Spray Booms	41xxx (ALL)	250009999 and Prior

**Subject:** Main Frame Tube Asm (42227-03) Dimensional Changes.

**Situation:** Starting with production in 2006, the Main Frame Tube Asm (42227-03) was modified to accommodate a lift ram with rubber anchor mounts. This slight change affects the fit of this part when used to repair units made during 2005 or before.



**Solution:** When using the Main Frame Tube Asm to repair units 2005 and older, additional parts will be required. The additional parts are:

- 2 - Adjustable Clevis (108-3250) 
- 2 - Clevis Pin (100-6541) 

Please contact your Authorized Toro Distributor with your questions or for your parts needs.