



Reel Motor (93-1375) Replacement (107-3531)

Product: Greensmaster 3200, 3200-D and 3250-D

Nov 9, 2009

Changed serial range

Affected Units:	Models:	Serial Numbers:
Greensmaster 3200	04380	50001 – 99999
Greensmaster 3200-D	04381	50001 – 99999
Greensmaster 3250-D	04383	200000101 - 230000600

Situation:

Use Reel Motor (107-3531) to replace Reel Motor (93-1375) on Greensmasters listed above.

Instructions:

The Greensmasters listed above have a Manifold Block that does not have an S6 valve incorporated into the reel circuit. This circuit configuration could cause the reel insert nuts to back off due to high torque loads.

Reel Motor (107-3531) addresses this issue by limiting torque loads during operation.

The Greensmasters listed above should use Reel Motor (107-3531) whenever a replacement for Reel Motor (93-1375) is required.

Do not order 93-1375 as it will cross reference to a Reel Motor (112-9200) which is inappropriate for this model.