



Replacement Fuel Filter Assembly or Spin-on Element

Groundsmaster 580-D Traction Unit

Model No. 117-9431

Model No. 117-9432

Installation Instructions

- Part Numbers 69-1750 and 69-1770 are no longer available from the manufacturer. The new filter Part No. is 63-8300.
- The new filter is not equipped with a water sensor probe, so the **Water in the Fuel** indicator light and associated alarm will no longer function.
- Secure the wire harness pig tail, previously connected to the probe, to prevent any damage.
- Drain water/fuel separator daily.
- Refer to the Operator's Manual for service procedures.