Form No. 3437-104 Rev A



Count on it.

Parts Catalog

GeoLink[®] CDMA Precision Spray System Kit

Multi Pro® 1750 or 5800 Turf Sprayer

Model No. 41633-Serial No. 32000000 and Up



Ordering Replacement Parts

To order replacement parts, please supply the part number, the quantity, and the description of each part desired.

Understanding Reference Numbers

Each identified part in an illustration has a reference number. The reference number for a part also appears in the parts list, along with other information about the part.

This catalog uses two special reference number formats, one to indicate parts in a service assembly and another to indicate the quantity of a given part in an illustration.

Service Assembly Reference Numbers

Parts in service assemblies have reference numbers in the form a:b. The a represents the reference number of the entire service assembly and the b represents a sequential number unique to each part within the service assembly.

For example, a wheel assembly might be identified by reference number 6, the tire by 6:1, the valve by 6:2, and the wheel by 6:3. When you order the assembly identified by reference number 6, you receive all parts identified by reference numbers 6:1,6:2, and 6:3. However, you may also order any part individually. Reference numbers of this type appear in illustration and in parts lists.


Reference Numbers Indicating Quantity

In an illustration, if a reference number indicates more than one part, the reference number has the form nX y. The n represents the quantity of the part, the X is the multiplication symbol, and the y represents the reference number.

For example, in an illustration, the reference number 2X 37 means that two of the parts identified by reference number 37 are indicated.

Contents

| 5800 Turf Sprayer GeoLink CDMA Precision Spray System Assembly | 4 |
|--|---|
| Multi Pro 1750 GeoLink CDMA Precision Spray System Assembly | 5 |



5800 Turf Sprayer GeoLink CDMA Precision Spray System Assembly

| Ref. | Part Number | Qty. | Description | Ref. | Part Number | Qty. | Description |
|------|-------------|------|---------------------------|------|-------------|------|---------------------------|
| 1 | 130-7306 | 1 | Reciever | 6 | 122-1650 | 1 | Harness-Wire, Adapter |
| 2 | 133-0410 | 1 | Control Console ASM | 7 | 140-1355 | 1 | Modem CI55-Lte |
| 2:1 | 131-3797 | 1 | Arm-Mount, Ram + | 8 | 139-6148 | 1 | Antenna ASM, CI55 |
| 2:2 | 130-7299 | 1 | Base-Mount, Ram ◆ | 9 | 138-6284 | 1 | Harness - Console To |
| 3 | 137-4258 | 1 | Controller - | | | | Modem, CI-55 |
| | | | Rate/Auto-Section, Asc-10 | 10 | 138-6285 | 1 | Harness - Modem To Power, |
| 4 | 122-1373 | 1 | Harness-Wire, Geolink | | | | CI-55 |
| 4:2 | 32180-043 | 2 | Resistor-120 Ohm | 11 | | 1 | Kit - Imu + Rtk Unlock ▲ |
| 4:3 | 218-578 | 1 | Fuse-Blade, 10 Amp | 11:1 | 130-7329 | 1 | Module-Imu |
| 4:4 | 32180-019 | 1 | Cover-Fuse, Single | 99 | 997-225 | 1 | Software: Geolink, X25, |
| 4:5 | 122-1404 | 2 | Terminator-Isobus | | | | Flash Drive ●■ |
| 5 | 122-1649 | 1 | Harness-Wire, Adapter | | | | |

Not illustrated


▲ Not serviced separately

Obtain parts from Toro[®] NSN[®] at 1-844-436-5465.

3437-104A

4

Optional Equipment



Multi Pro 1750 **GeoLink CDMA Precision Spray System Assembly**

| Ref. | Part Number | Qty. | Description | Ref. | Part Number | Qty. | Description |
|------|-------------|------|---------------------------|------|-------------|------|---------------------------|
| 1 | 130-7306 | 1 | Reciever | 6 | 122-1650 | 1 | Harness-Wire, Adapter |
| 2 | 133-0410 | 1 | Control Console ASM | 7 | 140-1355 | 1 | Modem CI55-Lte |
| 2:1 | 131-3797 | 1 | Arm-Mount, Ram 🕈 | 8 | 139-6148 | 1 | Antenna ASM, CI55 |
| 2:2 | 130-7299 | 1 | Base-Mount, Ram ◆ | 9 | 138-6284 | 1 | Harness - Console To |
| 3 | 137-4258 | 1 | Controller - | | | | Modem, CI-55 |
| | | | Rate/Auto-Section, Asc-10 | 10 | 138-6285 | 1 | Harness - Modem To Power, |
| 4 | 122-1373 | 1 | Harness-Wire, Geolink | | | | CI-55 |
| 4:2 | 32180-043 | 2 | Resistor-120 Ohm | 11 | | 1 | Kit - Imu + Rtk Unlock 🔺 |
| 4:3 | 218-578 | 1 | Fuse-Blade, 10 Amp | 11:1 | 130-7329 | 1 | Module-Imu |
| 4:4 | 32180-019 | 1 | Cover-Fuse, Single | 99 | 997-225 | 1 | Software: Geolink, X25, |
| 4:5 | 122-1404 | 2 | Terminator-Isobus | | | | Flash Drive ●■ |
| 5 | 122-1649 | 1 | Harness-Wire, Adapter | | | | |

Not illustrated
Not serviced separately
Obtain parts from Toro[®] NSN[®] at 1-844-436-5465.

Optional Equipment

Notes:

Notes:



Count on it.