



Groundsmaster® 300 Series

<u>Model/Serial Range:</u>	<u>Model Number:</u>	<u>Serial Numbers:</u>
	ALL	00000-99999

Subject: Recycler® PTO Shaft too short for other attachments.

Units equipped with Recycler Deck (Model 30716) must use PTO Shaft (93-9962) that is supplied with the deck. This PTO Shaft is shorter than the one supplied with the traction unit. The Recycler Deck PTO Shaft will not be able to connect the traction unit to attachments such as the Snow Blower 150 (Model 44910) or Debris Blower 2670 (Model 44524) because of the shorter length of the shaft.

If you have a Recycler Deck and will be connecting other attachments, such as a Snow Blower 150 or Debris Blower 2670, PTO Shaft (84-4890) is needed to complete the connection. The PTO Shaft is the correct length for these applications.

NOTE:

Traction units are equipped with PTO Shaft (84-4890) and Recycler Decks are equipped with PTO Shaft (93-9962) from the factory.