


TORO®

MODEL NO. 07399

PARTS
CATALOG**WORKMAN 3100**
AUXILIARY POWER UNIT KIT (AC GAS)

T-1784-2

AUX POWER UNIT

Ref. No.	Part No.	Description	No. Used
1	3257-7	Key - Woodruff	1
2	322-7	Screw - Hex. Hd. Cap	4
3	71-4411	Spacer	4
4	44-2230	Coupling - Rubber	4
5	92-2618	Drive Shaft Assembly	1
6	3296-29	Nut - Lock	4
7	87-7880	Pulley - Crankshaft	1
8	71-4410	Spacer	4
9	3296-15	Nut - Lock	2

Ref. No.	Part No.	Description	No. Used
10	3256-3	Washer - Flat	4
11	322-9	Screw - Hex. Hd. Cap	4
12	92-2616	Shaft - Drive	1
13	251-82	Bearing	2
14	87-2750	Spacer - Bearing	1
15	87-2740	Hub - Pulley	1
16	3256-28	Washer - Flat	1
17	80-8040	Decal - Caution	1