



THROTTLE CABLE ASSEMBLY	
MODEL NO. 58355 - 6900001 & UP MODEL NO. 58356 - 6900001 & UP	OPERATOR MANUAL ADDENDUM

Refer to the following “Throttle Cable Assembly” information in addition to the instructions on page EN-5 in the enclosed Toro Cultivator - Model No. 58355 Operator’s Manual.

Throttle Cable Assembly

IMPORTANT NOTE: The throttle cable housing must be fully seated into the trigger housing (Fig. 1) and into the carburetor mount (Fig. 2) for proper throttle operation.




Figure 1

1. Trigger housing 2. Throttle cable housing




Figure 2

1. Carburetor mount 2. Throttle cable housing