



Customer Service Bulletin Commercial Business Group

Groundsmaster® 325 Diesel Series

<u>Model/Serial Range:</u>	<u>Model Number:</u>	<u>Serial Numbers:</u>
	30739	50001-79999
	30741	50001-79999
	30788	50001-79999
	30795	50001-79999

Subject: R-Clamp Replacement Kit - Customer Direct Offer.

The metal R-Clamp that secures the positive battery cable and fuel return lines may start to chafe the outer cover of the positive battery cable and expose the inner cable wires to the environment and/or shorting out the battery by contacting the metal R-clamp or frame.

The Toro Company is offering an easy to install R-Clamp Replacement Kit (99-1295) that will be standard on future products and may be installed on all products listed above. This kit uses a polyethylene (plastic) type clamp to secure the positive battery cable and fuel return lines separately. Registered Owners (USA only) were contacted by mail in April of 1999.

If you did not receive a letter, but have a product affected by this program and would like to receive this kit free of charge, copy and complete the form below and Fax it to The Toro Commercial Service Department at (612) 887-7292.

TORO® GROUNDMASTER® UPGRADE PROGRAM			
Customer Name _____		_____	
Street Address _____		_____	
City _____	State ____	Zip _____	_____
Product Information:			
<u>Model #</u>	<u>Serial #</u>	<u>Model #</u>	<u>Serial #</u>
1) _____	_____	9) _____	_____
2) _____	_____	10) _____	_____
3) _____	_____	11) _____	_____
4) _____	_____	12) _____	_____
5) _____	_____	13) _____	_____
6) _____	_____	14) _____	_____
7) _____	_____	15) _____	_____
8) _____	_____	16) _____	_____