



## Customer Service Bulletin Commercial Business Group

---

### Workman<sup>®</sup> 3200 and 3300-D

<u>Model/Serial Range:</u>	<u>Model Number:</u>	<u>Serial Numbers:</u>
	07200	50195-50246
	07205	50210-50267
	07206	50001-50136

**Subject: Change to Rear Brake Assembly.**

An inner seal was added to Brake Drum (93-7128) to reduce debris build up in the Brake Drum. Brake Assembly (93-7125) and (93-7126) were changed to match the Brake Drum with the added seal. Units listed above were manufactured with the original style Brake Assemblies, however the parts catalogs provided with the machine illustrates the wrong brake parts.

This bulletin provides information on serial numbers of machines affected by the change and the interchangeability of the parts in the different Rear Brake Assemblies. Replacement brake parts for the units affected may be found in 1994 serial numbered parts catalogs.

	Brake Drum 87-1840 (Old)	Brake Drum 93-7128 (New)
Brake Assy. 93-7125 (New)	YES	YES
Brake Assy. 93-7126 (New)	YES	YES
Brake Assy. 87-3830 (Old)	YES	NO
Brake Assy. 87-3840 (Old)	YES	NO